

Form: rprocess

	fonday, 22/10/2007 2:17:22 PM inda Lacelle	Drange Cheet	Split2 12.12
		Process Sheet	
Customer Job Number Estimate Number P.O. Number This Issue Prsht Rev. First Issue Previous Run Written By Checked & Appr	: 22/10/2007 S.O. No. : : NC : // Type : SMALL/MED : 35032	Material Due Date	: ARM : D3560044 : D3560 UNDER REVIEW : N/A : C : 29/10/2007
Comment	Est Rev B ECN 987 07.10		
Additional Produ	uct		
Seq. #:	Machine Or Operation:	Description :	
1.0	M6061T6B0500X05000	6061-T6 Bar .50" x 5.0"	
	ment: Qty.: 1.3598 f(s)/Unit Total: 19 6061-T6 Bar 0.50" x 5.00"	9.0365 f(s)	
	Batch: 1/06/182	\sim	Tal 07/1/30 (4)
2.0	BAND SAW	BAND SAW	
Com	ment: BAND SAW	. 9	
3.0	Cut blanks 15.500" long	HAAS CNC VERTICAL MACHINING	W 07/1/30 (14)
ATACAN AT			3#1
Com	ment: HAAS CNC VERTICAL MACHINING #	1	
	1- Mill as per Folio FA696 Rev: 丛	NTS. NY	
	2-C'sink 0.196" hole on manual mill as	per dwg D3560	
4.0	3-Deburr per dwg D3560	INSPECT PARTS AS THEY COME	1/2/08 D.F 07/12/07
5.0	ment: INSPECT PARTS AS THEY COME OF QC8	2167	112/08 21 6/16/01
	ment: SECOND CHECK	SECOND CHECK	7/12/2 - 2
Com	Ment. SECOND CHECK		M 01/2.01 19
		1	/


Page 1



Date: , Monday, 22/10/2007 2:17:22 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 35298 Part Number: D3560044 Job Number: Seq. #: Machine Or Operation: Description: 6.0 D35921 PLATE Comment: Qty.: 1.0000 Each(s)/Unit Total: 14.0000 Each(s) PLATE 7.0 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 1-Weld assembly as per dwg D3560 STEP: 1- clean material (buff bracket and bottom of arm with blue pad) 2- set up bracket and arm on jig 3- preheat bracket and arm with torch 4- clean before welding with brush 5- set up machine to 135 amps 6- weld across bottom and top ends 7- reheat with torch (60) 8- on one side weld from bottom to top half way 9- same for other side (half way) 10- from half way point weld the rest of the first side (ease off pedal near end) 11- same for remaining side (ease off pedal near end) 8.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 9.0 QC9 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION 10.0 HAND FINISHING1 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1



Date: Monday, 22/10/2007 2:17:22 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 35298 Part Number: D3560044 Job Number: Seq. #: Machine Or Operation: Description: 11.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 12.0 D2808 Comment: Qty.: 1.0000 Each(s)/Unit Total: 14.0000 Each(s) Spacer 08-01-27 13.0 SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 08-01-29 1-Press bushing in D3560 arm per dwg D3562 14.0 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 15.0 PACKAGING : PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: inh 16.0 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE 08101 Job Completion run L008/1/29





D3560-1 ARM (-041, SHOWN) OR D3560-2 ARM (-042, OPPOSITE) D3592-1 PLATE, SEE DETAIL A

> D3560-041 ARM WELDMENT (SHOWN), D3560-042 ARM WELDMENT (OPPOSITE)

03560-3 ARM (-043, SHOWN) OR D3560-4 ARM (-044, OPPOSITE) D3592-1 PLATE, -

D3560-043 ARM WELDMENT (SHOWN), D3560-044 ARM WELDMENT (OPPOSITE)





DETAIL A (SCALE 1:1)



GENERAL NOTES

- 1) WELD PER QSI 004
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES

07.06.19



UNDER REVIEW


07.10.22 DC


	С		07.06.19	REMOVE POWE	DER COAT
	В		07.01.15	REDESIGN AS	WELDMENT, ADD POCKETS
	A		06.09.25	NEW ISSUE	
OPYRIGHT @ 2008 BY DART AEROSPACE LTD.	DESIGN	9	DRAWN BY	DART	DART AEROSPACE LTD.
HIS DOCUMENT IS PRIVATE AND CONFIDENTIAL NO IS SUPPLIED ON THE EXPRESS CONDITION HAT IT IS NOT TO BE USED FOR ANY PURPOSE	CHECKE	· H	APPROVED #	DRAWING NO. D3560	REV. C SHEET 1 DF 3
R COPIED OR COMMUNICATED TO ANY OTHER ERSON WITHOUT WRITTEN PERMISSION FROM	DATE			TITLE	SCALE


ARM WELDMENT


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOS OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.











DART AEROSPACE LTD	Work Order:	35297
Description: Arm	Part Number:	D3560-4
Inspection Dwg: D3560 Rev: B		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.507	+0.000/-0.001	.507				
Ø0.196	+0.005/-0.001	-196				
Ø1.000	+0.010/-0.001	1. 000				
Ø0.900	+0.010/-0.001	699				
0.500	+/-0.010	204				
0.250	+/-0.010	359				
0.275	+/-0.010	.976				
0.188	+/-0.010	.137				
2.000	+/-0.010	3 904				
1.750	+/-0.010	1.752				
1.702	+/-0.010	1.704				
Ø0.385 x 100°	+/-0.010 x 0.5°	304				
0.250 Deep	+/-0.010	.952			•	
		1 60-				_
		**				

Measured by: 2.F	Audited by:	Prototype Approval:	N/A
Date: 07/12/07	Date: 07/12/08	Date:	N/A

Revised by	Approved
KJ/JLM	
	KJ/JLM KJ/JLM

